SERVICE BULLETIN #1019

SUBJECT Condenser Spring Adjustment.

MODEL S44 & S55 DATE 4-8-58

The condenser spring, part number 51959, which projects from the bottom of the breaker box, is intended to make positive contact with the condenser case and to provide an adequate ground.

It is possible, upon removal of the breaker box cover, to bend the spring so that it will not make contact with the condenser when the breaker box cover is re-installed. Under these conditions the cover retaining screws do not provide adequate ground.

When difficulty in starting the engine is encountered, it may be due to this inadequate ground. We suggest that you check the condenser spring and bend it up so that when reinstalling the breaker box cover, pressure against the spring is necessary to line up the retainer screw holes.



LITHO IN U.S.A.