McCULLOCH

SERVICE BULLETIN #1161

SUBJECT CHAIN BREAKER REPLACEMENT BUSHING, P/N 56801

MODEL MISCELLANEOUS DATE 2/20/62

A service replacement Bushing, P/N 56801, is available for replacing a worn or damaged punch guide bushing in the McCulloch Chain Breaker, P/N 56800A.

The hole is undersize in the replacement bushing and must be reamed to fit the punch after the bushing is installed in the chain breaker base.

Reaming the hole to a diameter of 0.491 to 0.493 inch (1.25 cm) will result in the proper fit for the punch. A close fit is needed between the bushing and the punch to prevent any side movement of the punch and keep it centered on the rivet to insure a good, clean break.

COPYRIGHT 1962 McCULLOCH CORPORATION

LITHO IN U.S.A.