McCULLOCH CORPORATION

SERVICE BULLETIN

1534

MODEL: SP 125

February 13, 1973

SUBJECT: CLUTCH CHANGE

Most recent production (November, December, '72) of the Model SP 125 saw is built with redesigned clutch shoes. The new Shoe, P/N 88817, is 1/8-inch thinner than the previous production Shoe, P/N 86465, and permits a lighter clutch assembly with a higher clutch engagement speed.

Shoe	Part No.	Thickness
Old	86465	.645"
New	88817	.520"

It is important to note that the new, thinner Shoe, P/N 88817, must be installed in sets of 3. These shoes are not individually interchangeable with shoes, P/N 86465. Other clutch elements (rotor, spring, plates) remain the same.

This change to the new clutch shoe is effective on SP 125 saws as follows:

Model No.	S/N Prefix	Serial Nos.
600076B	12-	10001 - 10800
600076D	12-	10001 - 10600
600076J	12-	10001 - 10568

McCULLOCH CORPORATION

By Jack Carroll
Service Manager

Copyright 1972 by McCulloch Corporation

LITHO IN U.S.A.