McCULLOCH CORPORATION
SERVICE BULLETIN

1543

MODEL: Mini Mac 6, 6 Automatic, 1 and 1 Automatic

August 3, 1973

SUBJECT: SERVICE REQUEST

The improved fuel hose, P/N 83904, with expander tube, P/N 89789, announced in Service Bulletin 1541 was installed in Mini Mac saws as listed below:

	Model Number	Starting with Serial Number	
Mini Mac 1	600081H	12-51528 13-10001	All units with these numbers or higher numbers have the new improved fuel hose.
Mini Mac 1A	600080G	13-25801 14-10001	
Mini Mac 6A	600080U	13-55783 14-10001	
Mini Mac 6A	600080H	13-29814 14-10001	

We request that any Mini Mac Series units that come in for repair of any type, which do not fall in the above listed categories, be checked for signs of fuel leaks at the fuel hose to tank connection.

If any sign of leakage is found at the connection, we request that a new improved fuel hose be installed at no charge to the customer. Submit a Warranty Request to your McCulloch Distributor to obtain payment for the new fuel hose and labor. Labor for this repair will be based on the time allowed in the Flat Rate Labor Schedule; .3 of an hour, plus operation Z-1, .4 of an hour, for a total of .7 of an hour or $4.90.

If inspection of a unit does not reveal any leakage we request that you advise the customer that some units have leaked at the fuel hose connection. Show the customer how to inspect for leakage and suggest that he should make it a point to inspect regularly, especially after the unit has been in storage for an extended period.

McCULLOCH CORPORATION

By Jack Carroll
Service Manager

Copyright 1973 by McCulloch Corporation