McCULLOCH CORPORATION
SERVICE BULLETIN

1565

MODEL: Mini-Mac 1, 1A, 6, 6A

June 27, 1974

SUBJECT: Service Request

You may be aware that McCulloch Mini-Mac 1, 1A, 6 and 6A chain saws manufactured prior to April, 1973, have been reviewed by the Consumer Product Safety Commission because of the possibility of fuel leakage.

We are pleased to inform you that the Commission's proceedings against McCulloch have been dismissed. The problem was the result of the effect certain gasoline additives had on the Mini-Mac fuel hoses and McCulloch has taken the necessary steps to overcome the problem.

A stipulation of the dismissal is that McCulloch will communicate with owners of the saws in question, urging them to bring their saws to a servicing dealer for free installation of a new fuel hose.

Samples of a postcard being sent to Mini-Mac owners on record, a letter to non-servicing dealers, and a news release being delivered to selected communications media to notify all Mini-Mac 1, 1A, 6 and 6A owners affected are enclosed.

Your cooperation in this matter will be very much appreciated and will no doubt result in satisfaction among your customers. We, therefore, request that a new Fuel Hose Kit, P/N 90661, with plastic adapter, be installed at no charge to the customer on any Mini-Mac saw brought in for service under this program as listed in the tabulation below.

Submit a Warranty Request to your McCulloch Distributor to obtain payment for the new fuel hose and labor. Labor for this repair will be based on the time allowed in the Flat Rate Labor Schedule; .3 of an hour, plus operation Z-1, .4 of an hour, for a total of .7 of an hour or $4.90.

Mini-Mac 1		All units with serial numbers lower than those listed are subject to the free hose replacement program.
Model No. 600081H	S/N 12-55028	
Mini-Mac 1 Automatic		
Model No. 600080G	S/N 13-26690	
Mini-Mac 6		
Model No. 600081U	S/N 12-26201	
Mini-Mac 6 Automatic		
Model No. 600080U	S/N 13-61383	
Model No. 600080H	S/N 13-33311	

There will be no service required on any saw which has the new, plastic adapter type hose, P/N 90661. Such saws may be easily identified by the white plastic edge of the adapter protruding through the inspection slot at the bottom of the saw. (See Service Bulletin No. 1548).

McCULLOCH CORPORATION

By Jack Carroll
Director, Product Service

Enclosures

Copyright 1974 by McCulloch Corporation

LITHO IN U.S.A.