McCULLOCH

SERVICE BULLETIN # 1050

SUBJECT FILTER REPLACEMENT

MODEL MAC D30 and D36 DATE 2/9/59

The urathene plastic filter, P/N 50379, in the fuel pick up, P/N 50082, is replaced by a felt filter, P/N 50124A.

The felt filter has the ability to collect fines and absorb and retain moisture from the fuel, thus preventing dirt and water from passing into the carburetor. An excess accumulation of dirt and moisture in the felt filter will restrict the flow of fuel, or, under very low temperature conditions, will freeze, stopping fuel flow entirely. Because of this, the felt filter should be inspected frequently and when dirt or moisture accumulation becomes excessive, the filter should be removed and a new, clean one installed.

All customers should know how to inspect and replace the felt filter, P/N 50124A, and be informed of the importance of maintaining an adequate replacement supply.

COPYRIGHT— 1959 McCULLOCH CORPORATION

LITHO IN U.S.A.