McCULLOCH

SERVICE BULLETIN #1179


MODEL 1-92

DATE 6/6/62

SUBJECT New Cylinder Crankcase Assembly, P/N 58551 and Reed Valve Plate, P/N 57656B

Cylinder Crankcase Assembly, P/N 58162, for Model 1-92 engines is no longer available. When required for service replacement, new Cylinder Crankcase Assembly, P/N 58551 (also used on Model 1-93 engines) will be furnished.

When ordering Cylinder Crankcase Assembly, P/N 58551, for Model 1-92 engines, new Reed Valve Plate, P/N 57656B, must also be ordered. The old reed valve plate (P/N 57656A) will not fit and cannot be used with the new cylinder crankcase.



←Reed Valve Plate, P/N 57656B

Shape of old Reed Valve Plate, P/N 57656A, shown by dotted line.

COPYRIGHT 1962 McCULLOCH CORPORATION

LITHO IN U.S.A.