McCULLOCH SERVICE BULLETIN

NO. 1571

MODEL SP 125C, SP 105, PM 105, 895C DATE August 21, 1974

SUBJECT Piston Assembly Changes

A slight change in the chamfer at the end of the piston pin has made it possible to standardize the piston pin for all Model SP 125C, SP 105, PM 105 and 895C engines. To simplify parts order, installation and assure full interchangeability, the standard pin is being included in service piston assemblies for all of the above engines. This assembly change is shown in the service lists as follows:

SP 125C

Part No.	Description	Units Per Assy.
85539	Piston & Pin Assembly	1
85608	. Ring Set - Piston	1
85273	. Ring - Retaining	2
89204	. Pin - Piston	1

SP 105, PM 105, 895C

Part No.	Description	Units Per Assy.
89251	Piston & Pin Assembly	1
89250	. Ring Set - Piston	1
85273	. Ring - Retaining	2
89204	. Pin - Piston	1

The addition of the pin to the piston assembly results in the following change in list prices for the complete assembly.

Part No.	Description	Manufacturer's Suggested List Price
85539	Piston & Pin Assembly	$17.95
89251	Piston & Pin Assembly	$17.60
89204	Pin - Piston	$ 2.40

McCULLOCH CORPORATION

Jack Carroll
Director, Product Service