McCULLOCH SERVICE BULLETIN

NO. 1627

MODEL 1. Mini Mac Series, PM6, SP 40
2. Mini Mac 35 AUTO SHARP

DATE November 1, 1976

SUBJECT 1. Flywheel Nut Torque, Mini Mac Series, PM-6, SP 40.
2. Auto Sharp AS370G Parts Information

---

1. Torque for Flywheel Nut, P/N 110970, used with Flywheel & Pawl Assembly, P/N 91961, and Crankshaft, P/N 91932, has been increased from 170 to 175 pound x inches (19.2 to 19.8 N.m.) to 190 to 200 pound x inches (21.5 to 22.6 N.m.).

In order to apply and maintain the proper torque, be certain the flywheel and crankshaft tapers are clean and free of oil.

NOTE: Please change the footnote concerning flywheel nut torque in all current illustrated parts lists for the subject model chain saws.

---

2. Pricing and stocking information for AUTO SHARP AS370G chain and repair parts is listed in the following table.

Part No.	Description	Price	Stock Code
92600N	Chain -AS370G 49 C.L.	$14.49	A
92602	Cutter-left hand	.80	A
92603	Cutter-right hand	.80	A
92604	Guard link	.18	A
92605	Repair kit	.68	A

McCULLOCH CORPORATION

Product Service
Department

©U.S.A. 1976 – McCULLOCH CORPORATION
Printed in U.S.A.