SERVICE BULLETIN #1002

SUBJECT Gear Case Assembly
Modification for Oiler Push Rod

MODEL 55 DATE 9-19-57

A new and heavier oiler push rod, part number 51343, was introduced with engine serial number 55-6000, in order to obtain greater pressure and efficiency in the oil pump. With this new rod, a new oiler button, part number 51771, and a new push rod extension, part number 51930, were also introduced.

The gear case assembly, part number 51893A, can accomodate the heavier push rod, however, the earlier gear case assembly, part number 51604A, must be modified to enlarge the push rod bore to .202/.208 of an inch. This may be done with a 13/64 inch, #5 or #6 drill. When the hole is made larger, the new push rod with a diameter of .178 of an inch will be allowed free movement to supply the chain with an increased quantity of oil.

LITHO IN U.S.A.