SERVICE BULLETIN #1014

SUBJECT Spark Plug - Wire Assemblies. New, Improved Wire

MODEL ALL DATE 2-26-58

An improved secondary wire lead (Coil to Spark Plug) is available for all McCulloch Chain Saw Models. The new wire is more flexible, for ease of installation and removal, and is more resistant to cracks and checks, for longer service life, than wires previously used.

In order to minimize inventory problems at both factory and Distributor-Dealer levels, the new wire lead will be sold for all models under two part numbers only. The part numbers are: 38049 and 52547. (See Table for model designations.)

The wire assemblies are intended for the specific models as listed in the following Table. For some models, in order to provide a correct fit, it will be necessary to shorten the wire assembly as noted in the Table.

TABLE

38049 For Models:	52547 For Models:		
5-49	33	7-55	3-25**
D-44*	33A	99	47**
55*	33B	7FP	4-30**
	S-33	99FP	4-30A**
	35	S-44	73**
	39	S-55	49**
			77**

* Shorten wire assembly to 7 inches for models indicated.
** Shorten wire assembly to 2-3/4 inches for models indicated.

List Prices for the new, improved secondary lead wire assemblies are:

38049----------.60 52547----------.48

LITHO IN U.S.A.