McCULLOCH


SERVICE BULLETIN #1062

MODEL **S44**, S44A, S55, S55A DATE 7/9/59

SUBJECT **CRANKSHAFT IDENTIFICATION**

The crankshaft, P/N 55005 (used on Models S44 and S55), and the crankshaft, P/N 55257 (used on Models S44A and S55A), are similar in appearance. Because of this similarity, the wrong crankshaft may be installed in an engine unintentionally.

To avoid any mix-up between these two crankshafts and to provide a quick means of identification, a large spot of yellow dykem is now put on the counterweight area of the 55257 crankshaft.



COPYRIGHT— 1959 McCULLOCH CORPORATION

LITHO IN U.S.A.