
McCULLOCH

SERVICE BULLETIN # 1079

SUBJECT **HANDLE BRACE BOLT**

MODEL **1-40**, 1-50, 1-60 DATE 12/15/59

If the Handle Brace Bolts, P/N 100882, are bottoming out in the crankcase cylinders of Models 1-40, 1-50, and 1-60 saw engines, add a plain Washer, P/N 100004, under the head of each Handle Brace Bolt.



COPYRIGHT— 1959 McCULLOCH CORPORATION

LITHO IN U.S.A.