McCULLOCH

SERVICE BULLETIN #1080

SUBJECT **SPARK PLUG WIRE ASSEMBLIES**

MODEL **ALL**

DATE **12/14/59**

This Bulletin replaces Service Bulletin #1014

In keeping with the desire to reduce inventory problems, and avoid unnecessary stocking of replacement parts, three Spark Plug Wire Assemblies (P/N's 50120, 51851 and 52547) will provide for service replacement on all McCulloch chain saw engines.

The table below lists the spark plug wire assembly number and the model engines on which it is used. For some models, it will be necessary to shorten the wire assembly to provide a correct fit.

SPARK PLUG WIRE ASSEMBLIES

P/N 50120	P/N 52547	
1-40	1-70	S-44
1-50	1-80	S-55
1-60	MAC 35A	S-44A
MAC D30	33	S-55A
D36	33A	3-25 **
5-49	33B	47 **
D-44 *	S-33	4-30 **
55 *	35	4-30A **
	39	49 **
P/N 51851	7-55	73 **
	7FP	77 **
MC 10	99FP	99

* Shorten wire assembly to 7 inches.

** Shorten wire assembly to 2-3/4 inches.

COPYRIGHT— 1959 McCULLOCH CORPORATION

LITHO IN U.S.A.