McCULLOCH

SERVICE BULLETIN #1084

SUBJECT **PISTON RING SETS**

MODEL **7-55**


DATE 2/29/60

Two Piston Ring Sets, P/N's 24804 and 28809, are available for service replacement on Model 7-55 chain saw engines. Use P/N 24804 Ring Set with the wide groove piston, and P/N 28809 Ring Set with the narrow groove piston (see illustrations below).

Page 7 of the Master Parts Price List, November 1, 1959, showing P/N's 24804, 24805, 24806, and 24807 replaced by P/N's 28809, 28810, 28811, and 28812, is in error. Cross out P/N's 28809, 28810, 28811, and 28812, and add the prices listed below for the wide groove piston ring set.

NARROW GROOVE PISTON

WIDE GROOVE PISTON



Ring Set Required:		Price
28809	Standard	- $2.25
28810	.010 O.S.	- 2.25
28811	.020 O.S.	- 2.25
28812	.030 O.S.	- 2.25

Ring Set Required:		Price
24804	Standard	- $1.05
24805	.010 O.S.	- 1.05
24806	.020 O.S.	- 1.05
24807	.030 O.S.	- 1.05

The above changes will be incorporated in the next issue of the Master Parts Price List.

NOTE: Model 7-55 engines have used pistons with and without carbon ring grooves. The presence or lack of a carbon ring groove does not affect interchangeability of 7-55 pistons.

COPYRIGHT 1960 McCULLOCH CORPORATION

LITHO IN U.S.A.