McCULLOCH

SERVICE BULLETIN #1106


MODEL 1-71, 1-81 DATE 9/30/60

SUBJECT PREVENTION OF AIR LEAKAGE THROUGH FUEL TANK WICK

To prevent air leakage through the fuel pick-up, Fuel Tank Wick, P/N 55405, should be used in place of fuel tank wick, P/N 55676, on the above listed engines. The 55405 Fuel Tank Wick was used on 1-70 and 1-80 engines and is being installed in production 1-71 and 1-81 engines.


Dealers should change their 1-71 and 1-81 Illustrated Parts Lists by crossing out P/N 55676 (Figure 2, Index Number 17) and adding P/N 55405.

NEW PART



P/N 55405

REPLACED PART



P/N 55676

COPYRIGHT 1960 McCULLOCH CORPORATION

LITHO IN U.S.A.