McCULLOCH

SERVICE BULLETIN #1107

SUBJECT ELIMINATION OF CHOKE AND OILER BUTTON SWELLING.

MODEL 1-41, 1-51, 1-61 DATE 9/30/60

Because of the hot weather which is still present in many sections of the country, we have been receiving reports of the choke and oiler button shafts swelling and sticking or binding in the airbox. Small swellings can be harmlessly removed by lightly sanding the swollen part of the shaft with a small piece of sandpaper. However, if the swelling is too great, heavy sanding will damage or weaken the shaft. If light sanding will not eliminate the affected area, replace the button with a new one.



COPYRIGHT 1960 McCULLOCH CORPORATION

LITHO IN U.S.A.