McCULLOCH

# SERVICE BULLETIN #1108

SUBJECT NEW STARTER ASSEMBLY - P/N 57117A


MODEL 1-41, 1-51, MC-6, and MC-10 DATE 10/17/60

An improved Starter Assembly, P/N 57117A, is available for service replacement on Model 1-41 and 1-51 chain saw engines and MC-6 and MC-10 kart engines which have starter kits installed. The new Starter Assembly contains a redesigned Starter Drum and Starter Ratchet which increase service life and provide easier disassembly when service replacement is necessary (see illustration below).


| PART | NEW NO. | REPLACED NO. |
|---|---|---|
| Starter Assembly | 57117A | 57117 |
| . Drum - Starter | *57587 | 57074 |
| . Ratchet - Starter | *57586 | 57072 |

*Matching parts which must be used together.

When replacing a 57074 starter drum, also replace the 57072 ratchet; and conversely, when replacing the 57072 ratchet, replace the 57074 starter drum. Thread sizes of the new and the replaced parts are different and therefore they cannot be interchanged separately.




REPLACED PARTS




NEW PARTS

COPYRIGHT 1960 McCULLOCH CORPORATION

LITHO IN U.S.A.