McCULLOCH

SERVICE BULLETIN # 1144

MODEL 1-85

DATE 10/5/61

SUBJECT PITCH CHANGE IN SPROCKET RESULTS IN MORE EFFICIENT OPERATION

To obtain more efficient operation, the 7 tooth, 9/16-inch pitch Sprocket, P/N 36791A, is now installed as standard equipment on Model 1-85 chain saws, replacing the 1/2-inch pitch sprocket called out in the Illustrated Parts List. This change was effective with Engine Serial No. 1182.

Using the larger pitch sprocket and SP-9 chain on the chain saw permits the user to take full advantage of the extra operating torque available from the Model 1-85.

The 9/16-inch pitch Sprocket, P/N 36791A, is a direct replacement for the 1/2-inch pitch Sprocket, P/N 36644A, listed as standard equipment in the Illustrated Parts List, and will back-fit all Model 1-85 chain saws.

To prevent possibility of damage to either saw chain or sprocket, make certain they are of the same pitch before installing the saw chain on a Model 1-85.

COPYRIGHT 1961 McCULLOCH CORPORATION

LITHO IN U.S.A.