McCULLOCH


SERVICE BULLETIN #1196

SUBJECT IMPROVED CLUTCH GUARD ASSEMBLY, P/N 53542A

MODEL 1-43, 1-46, 1-53 DATE 9/3/62

An improved Clutch Guard Assembly, P/N 53542A, designed for increased service life, is now available for Model 1-43, 1-46, and 1-53 engines. This new clutch guard assembly replaces the old clutch guard assembly, P/N 53542, and will be furnished on all replacement orders for Clutch Guard, P/N 50072C or P/N 50072D.

New Clutch Guard Assembly, P/N 53542A includes a new Clutch Guard, P/N 53854, and a new Bar Adjusting Screw, P/N 53853. Other differences in the new clutch guard assembly consist of relocation of the bar adjusting screw locknut and the washers. These differences are shown in the accompanying illustration.



COPYRIGHT 1962 McCULLOCH CORPORATION

LITHO IN U.S.A.