McCULLOCH CORPORATION
SERVICE BULLETIN

1480

MODEL: MAC 10 Series

October 7, 1969

SUBJECT: CARBURETOR FUEL PUMP DIAPHRAGM

A recent change in the manufacture of Walbro carburetors for MAC 10 Series engines has resulted in the elimination of Check Valve Diaphragm, P/N 67498, made possible by a change to Fuel Pump Diaphragm, P/N 83114, made of a new and improved material to replace Fuel Pump Diaphragm, P/N 67497.

For replacement of either the check valve diaphragm, or the former fuel pump diaphragm, order new Fuel Pump Diaphragm, P/N 83114.

When installing Fuel Pump Diaphragm, P/N 83114, discard Check Valve Diaphragm, P/N 67498.

McCULLOCH CORPORATION

Jack Carroll
Service Manager

Copyright 1969 by McCulloch Corporation

LITHO IN U.S.A.