McCULLOCH CORPORATION
SERVICE BULLETIN

1509

MODEL: SUPER PRO-125

November 16, 1971

SUBJECT: GENERAL SERVICE INFORMATION

Enclosed is a copy of a "General Service Information Bulletin" (S.I. 38) covering the various procedures used to service the Super Pro-125 model saw.

Please note that this bulletin also provides information about improvements made on this model over the CP-125, specifications and the tools needed to service the unit.

McCULLOCH CORPORATION

By Jack Carroll
Service Manager

Copyright 1971 by McCulloch Corporation

LITHO IN U.S.A.