McCULLOCH CORPORATION
SERVICE BULLETIN


1539

MODEL: 10 Series, SP 80, SP 81, SP 60, PM 60

SUBJECT: PULSE PUMP GASKET


April 22, 1973

An improved Pulse Pump Gasket, P/N 89642, is now being used on SP 80, SP 81, SP 60, PM 60, and Mac 10 Series chain saws. The new gasket provides better alignment on saws with single screw pulse pump mounting. On earlier Mac 10 Series saws with three screw mounting, the old gasket, P/N 88782, must be used. Differences between the new gasket and the earlier gasket may be noted in the size of the screw holes as illustrated.



OLD

Mac 10 Series
(3 Screw Mounting)



NEW

Mac 10 Series
(1 Screw Mounting)
SP 80, SP 81
SP 60, PM 60

Use the illustration above to determine the proper replacement.

McCULLOCH CORPORATION

By Jack Carroll
Service Manager

Copyright 1973 by McCulloch Corporation

LITHO IN U.S.A.