McCULLOCH CORPORATION
SERVICE BULLETIN

1563

MODEL: Mini-Mac June 16, 1974

SUBJECT: Improved Venting Fuel/Oil Cap, P/N 90922

A ring of polyurethane is now being inserted between the black portion of the fuel/oil cap and the "Poly Seal" insert of the cap. This polyurethane ring greatly reduces the amount of fuel which can escape through the cap vent when a unit is used in either felling position (muffler up or down), or with the bar in a steep up or down angle.

The caps, new and old, can be identified visually. Hold the cap upside down in good light. If you can see the polyurethane under the "Poly Seal", it is a new cap; if you cannot see the polyurethane, it is an old cap.

The improved cap is being installed on current production units (on both oil and fuel tank sides) and began with Mini-Mac 35, Model 600091U, Serial Number 11-45701 and Mini-Mac 30, Model 600093U, Serial Number 11-54501.

McCULLOCH CORPORATION

Jack Carroll
Director, Product Service