McCULLOCH SERVICE BULLETIN

NO. 1574

MODEL Mini-Mac 30, 35 DATE September 16, 1974


SUBJECT IMPROVED THROTTLE TRIGGER


Trigger, P/N 83878, has been improved to provide better retention of the rod. With this improvement, the clip described in Service Bulletin #1560, to retain the throttle rod in the trigger, is no longer required. The improved Trigger, P/N 83878, was first installed in Mini-Macs as follows:

Mini-Mac 30 (Model 600093U) beginning with serial number 11-92500
Mini-Mac 30 (Model 600093B) beginning with serial number 11-10901
Mini-Mac 35 (Model 600091U) beginning with serial number 11-70603

The new trigger will backfit on all Mini-Mac saws which used the old trigger.

The old and the new trigger may be identified by the shape of the slot end as illustrated below.





McCULLOCH CORPORATION

By Jack Carroll
Director, Product Service

Copyright 1974 by McCulloch Corporation

LITHO IN U.S.A.