# McCULLOCH SERVICE BULLETIN

NO. 1593

MODEL All 10 Series Including Anti-Vibration Models DATE December 24, 1975

SUBJECT Oil Pickup Hose Kit, P/N 91509.

An improved Oil Pickup Hose Kit is now available to replace Oil Pickup Hose Assembly, P/N 62123B.

The new Oil Pickup Hose Kit improves the dry priming and check valve operation of the manual oiler.

The kit consists of the following parts.

| Part No. | Description | Qty | Mfg. Suggest. List Price | Stocking Code |
|---|---|---|---|---|
| 91509 | Oil Pickup Hose Kit | 1 | $1.50 | A |
| 91672 | . Hose Assy - Oil pickup | 1 | 1.20 | A |
| 91668 | . Valve - Check | 1 | .15 | A |
| 91669 | . Gasket - Pump body | 1 | .15 | A |

It is important that all three components are used when replacing Oil Pickup Hose, P/N 62123B.

Current production units that have these changes are listed below.

| Model Name | Model Number | Serial Number |
|---|---|---|
| Pro 10-10A | 600013B | 12-13001 and up |
| | 600013E | 12-10001 and up |
| | 600013K | 12-12501 and up |
| | 600013U | 12-27493 and up |
| PM 55 | 600031E | 12-10001 and up |
| | 600031U | 12-12432 and up |
| SP 60 | 600037D | 14-12001 and up |
| 7-10A | 600052B | 16-11001 and up |
| | 600052D | 16-11001 and up |
| SP 81 | 600438B | 14-12143 and up |
| | 600438D | 14-12209 and up |
| | 600438E | 14-10001 and up |

For these units, individual parts may be ordered for service requirements.

McCULLOCH CORPORATION

Product Service
Department

©U.S.A. 1975 - McCULLOCH CORPORATION

Printed in U.S.A.