McCULLOCH SERVICE BULLETIN

NO. 1623

MODEL 7-10A Chain Saw

DATE November 1, 1976

SUBJECT 1. Model Number 600052D (16-)
2. Model Number 600052 (17-)

---

1. Beginning with Serial Number 16-16001, 7-10A chain saws, Model Number 600052D, are equipped with:

   1. A two needle Carburetor, P/N 87666.
   2. Fuel Tank Cover, P/N 88650.
   3. Idle Adjustment Screw, P/N 87932.
   4. Carburetor Adjustments Boot, P/N 87665.

   These changes are included in IPL, P/N 92389A.

---

2. 7-10A chain saws now being manufactured are identified by Model Number 600052 and Serial Number Prefix 17-.

The Illustrated Parts List for this model is P/N 92389A. Your Distributor should provide you with a copy of this IPL in the near future if he has not already done so. This IPL supersedes and replaces IPL, P/N 92048.

Improvements and changes included in this model are:

1. A new combination "Safety Trigger and Throttle Latch" has been added. The safety trigger is designed to prevent accidental acceleration of the engine. The throttle latch is provided to hold the throttle partially open during starting.

   Owner's Manual Addendum, P/N 92932, explains operation of the combination "Safety Trigger and Throttle Latch."

2. A new pulse pump seal has been added to improve pump sealing and performance. This new seal, made of aluminum with a rubber bonding, provides improved sealing and performance. It also acts as a shock absorber to cushion the pump piston and therefore increases the life of the piston.

   NOTE: Pump Clamp, P/N 89114, is not required when Pulse Pump Seal, P/N 92818, is used.

Information concerning parts used in the 7-10A, Model Number 600052, Serial Number Prefix 17-, which were not listed in the previous 7-10A Illustrated Parts List, is presented in the following table.

©U.S.A. 1976 – McCULLOCH CORPORATION
Printed in U.S.A.

IPL Location	Part Number	Description	Qty	Mfg. Sugg. List Price	Stock Code
Figure 1	88650	Cover-Fuel tank	1	$ 7.30	A
"	87932	Screw-Idle adjust	1	1.80	A
"	87665	Boot-Carburetor adjust	1	1.25	A
"	110473	❶ Screw-Skt hd 10-24 x 1-5/8	1	.29	A
"	104560	❷ Screw-Skt hd 10-24 x 1-1/2	1	.34	A
"	110861	Screw-Skt hd 10-24 x 1-7/8	1	.14	A
Figure 6	87666	Carburetor Asy	1	25.40	A
Figure 7	84183A	Kit-Fuel Tank/Control	1	20.00	A
"	92152	Spring-Trigger	1	.10	A
"	92151	Trigger-Throttle	1	.70	A
"	105654	Pin-Roll 1/8 x 7/8	1	.11	A
"	92154	Spring-Trigger release	1	.10	A
"	92153	Release-Trigger	1	.35	A
"	68522A	Seal-Throttle rod	1	1.60	A
Figure 8	110969	Screw-Hex hd 8-32 x 1/2	1	.13	A
"	110338	Screw-Pan hd 8-32 x 1/2	2	.11	A
"	89115A	Pump Asy-Pulse	1	15.20	A
"	92818	Seal-Pulse pump	1	2.00	A
"	92844	Spring-Outlet valve	1	.35	A
"	89711A	Crankcase Asy	1	52.15	A

❶ Screw, P/N 110473, should be item 71 in the parts list. It is the bottom muffler screw.

❷ Screw, P/N 104560, should be replaced in the IPL by Screw, P/N 110861. Screw, P/N 110861 should be item 69 in the parts list. It is the top muffler screw.

NOTE: Items 15 and 16 in Figure 2 should be listed as part of CHAIN BRAKE Asy, P/N 91278, and Housing Asy, P/N 91249. Please place two dots before the descriptions of items 15 and 16.

McCULLOCH CORPORATION

Product Service
Department