McCULLOCH SERVICE BULLETIN


NO. 1632

MODEL SP 40 DATE April 1, 1977

SUBJECT 1. Ignition Switch Kit, P/N 92649 2. Correct CHAIN BRAKE Assembly on 13-level

1. Ignition Switch Kit, P/N 92649, is now available as service replacement for SP 40 chain saws with serial numbers prefixed 13-. The new switch has a male connector which replaces screw used to hold ignition wire assembly to terminal. This kit will not backfit on 12-level SP 40 saws. Ignition Wire Kit, P/N 58387, will continue to be used on these models.

2. Because of dimensional changes in shroud design two CHAIN BRAKE assemblys are used as service replacement on SP 40 chain saws with serial numbers prefixed 13-. CHAIN BRAKE Assembly, P/N 90570B, is used on units with serial numbers 15982 and below, CHAIN BRAKE Assembly, P/N 92594, is used on units with serial numbers 15983 and above.



P/N 90570B P/N 92594

©U.S.A. 1977 – McCULLOCH CORPORATION
Printed in U.S.A.