McCULLOCH

SERVICE BULLETIN

NO. 1651

MODEL Various

DATE September 1, 1977

SUBJECT
1. Mac 10-10, 10-10A IPL, P/N 92374
2. 7-10 Power Unit (OEM) IPL, P/N 92372
3. Mac 140 600022S (11-)
4. Changes to Chains, Bars, and Accessories Catalogue, ADV 190397
5. Bracket Kit, P/N 83204
6. Generator Propane Gas Conversion Kits

---

1. Illustrated Parts List, P/N 92374, for Mac 10-10 and 10-10A chain saws is now available. Your distributor should provide you with a copy of this IPL in the near future if he has not already done so. IPL P/N 92374 supercedes and replaces IPL P/N 87798, and can be used as a master IPL for all Mac 10-10 and 10-10A chain saws.

---

2. Illustrated Parts List, P/N 92372, covering 7-10 Power Units (OEM) Model Numbers 600261D and 600261E, Serial Number prefixes 11-, 12-, 13-, and 14-, is now available. IPL P/N 92372 will serve as a master parts list for the 7-10 OEM.

---

3. The following addition should be made to the Mac 140 IPL, P/N 93367.

   a. Page 1, Models and Serial Number listing; add 600022S to Models and Serial Number prefix 11- for this model.

   b. Figure 4, Item 19, Spark Plug; add suffix letter "S" after the description.

---

4. The following changes should be made to page 16 of Chains, Bars, and Accessories Catalogue, ADV 190397.

   a. Ear Protection--Sound Barrier Section; change P/N CP254TSM to P/N 155A.

   b. Sound Silencer Ear Plugs; change P/N AC48M to EP100G. Delete the price listed for this item since this is controlled by the manufacturer and we have no way of knowing when it will change.

   c. Suspensions; delete suffix letter M from P/N HC424M. Also delete HC425M as this item is no longer available.

   d. Winterliner; delete suffix letter M from P/N WL11M.

Printed in U.S.A.

5. Bracket Kit, P/N 83204, is no longer available as a kit for service replacement. Air Cleaner Bracket, P/N 69952, should be ordered in its place. All orders for Bracket Kit, P/N 83204, will be filled with Air Cleaner Bracket, P/N 69952. The original hold down screws should be used as fasteners for the replacement bracket.

6. Some old literature contains incorrect part numbers regarding which propane gas kits fit the H-1500 and H-2000 model generators. The correct kit part numbers are:

Model	Kit Part Number
H-1500	21708
H-2000	21708
Mac 1500 (Mark I)	21500
Mac 2000 (Mark II)	21500

McCULLOCH CORPORATION

Product Service Department