
# McCULLOCH SERVICE BULLETIN

NO. 1685

MODEL Power Mac 300 Series DATE March 1, 1979

SUBJECT (1) Bar Spacer, P/N 93148. (2) Handle/Throttle Trigger Screw, P/N 110706.

1. Bar Spacer, P/N 93148 (PM 310): An additional oil slot has been added. Both slots match with the oil outlet. Therefore, the spacer can't be installed "upside down". Either side up is correct. The part number is unchanged.



2. Screw, P/N 110706 (PM 300 Series), should now be used to hold the trigger and handle assemblies temporarily in place while servicing the saw. This screw should currently be in stock since it is used to secure the stop switch wire assembly and the ignition switch contact to the handles of PM 300 Series models. This screw replaces Screw, P/N 110232. All back orders for P/N 110232Z will be cancelled. P/N 110706Z is the correct order number.

McCULLOCH CORPORATION

Product Service Department

© U.S.A. 1978 – McCULLOCH CORPORATION