McCULLOCH SERVICE BULLETIN

NO. 1699

MODEL VARIOUS

DATE MAY 16, 1980

SUBJECT 1. STARTER COVER, PART NUMBER 87672

2. WARRANTY CLAIM/REPORT FORM, PART NUMBER 94474
3. CLAIM CHECK PACKAGE, PART NUMBER 87790
4. SPUR SPROCKET/DRUM ASSEMBLY, PART NUMBER 95384

1. Starter Cover, Part Number 87672, has been replaced by Starter Cover, Part Number 91084, on all 10 series saws except on the SP 70. Continue to order Starter Cover, Part Number 87672, for SP 70 units. Please make this change on all 10 series Illustrated Parts Lists.

PART NUMBER	DESCRIPTION	MFG. SUGGESTED LIST PRICE	STOCK CODE
87672	Starter Cover (SP 70)	6.45	C
91084	Starter Cover (10 series saws)	6.45	A

2. A price change is now in effect for Warranty Claim/Repair Form, Part Number 94474. The manufacturers suggested list price for Warranty Claim/Repair Forms, (package of 100) Part Number 94474, is $7.50. When this form is used for a warranty repair, a credit of $.04 will be issued.

3. When ordering Claim Check Package, Part Number 87790, please note you are ordering a package of 500 claim checks and not an individual piece. Example: If you are ordering (5) of Part Number 87790, you will receive 2,500 claim checks. Therefore, we request that you do not place any orders in excess of 10 Claim Check Package, Part Number 87790. All orders in excess of 10 (5,000 claim checks) will be adjusted to this limit.

4. Recent production of Mac 100 and Power Mac 300 series units were manufactured using a spur type, .375 pitch, sprocket. In addition, the spur sprocket was substitued for "clover leaf" sprocket, Part Number 94995, on some recent parts shipments.

The spur sprocket/drum/bearing is now available as a service part under Part Number 95384. Initial orders for the spur sprocket will be shipped in regular packaging, but in the near future, spur sprockets will be skin packed only.

PART NUMBER	DESCRIPTION	MFG. SUGGESTED LIST PRICE	STOCK CODE
95384	Sprocket/Drum/Bearing	7.49	C
. 213101	Washer-10.06 x 30 x 1 (pkg. of 10)	1.00	A
. 91222	Bearing	1.60	B

McCULLOCH CORPORATION

Product Service Department

Printed in U. S. A.