McCULLOCH SERVICE BULLETIN

NO. 1708

MODEL: ALL (Noted) DATE: DECEMBER 1, 1980

SUBJECT: 1. Master Parts Price List, ADV 140014-R10
2. Bar Adjustment Screw, P/N 94362
3. Service Replacement Cylinder on Super Pro 80, 81, 81E, Pro Mac 850, 800

---

1. The following changes and additions to Master Parts Price List, ADV 140014-R10, are required:

A. Some part numbers listed in section 1 are repeated in section 2 with different prices. When ordering parts, please refer to the prices represented in section 2 listed below:

PART NUMBER	DESCRIPTION	MFG. SUGG. LIST PRICE
214204V	Spark Arrestor Screen - 100, 300 Series (5 pack)	$16.50
214205V	Spark Arrestor Screen - 600 Series (5 pack)	10.75
214207V	Bucking Spike - 300 Series (5 pack)	4.75
214208V	Bucking Spike - 600 Series (5 pack)	35.00
214212V	300 Series Tool Kit (5 pack)	54.75
214220V	Scrench - 300 Series (5 pack)	16.45
214221V	Scrench - 600 Series (5 pack)	16.45
214222V	Auto Sharp Grinder Assembly (5 pack)	32.25
214223Z	Spark Plug (10 pack)	22.50
214224Z	Air Filter - 100 Series (10 pack)	15.50
214225Z	Air Filter - 300 Series (10 pack)	9.50
214226Z	Air Filter - 600 Series (10 Pack)	20.50

B. Part number 214245V is incorrectly listed and should be changed to P/N 214345V. Part number 214246 is incorrectly listed and should be changed to 214346.

Printed in U.S.A.

C. Part numbers and prices for String Trimmer Accessories were ommitted from this Master Parts Price List. Please include the following numbers and prices for a complete list.

PART NUMBER	DESCRIPTION	MFG. SUGG. LIST PRICE	STOCK CODE
95874	PKG - Wraparound Guard	$16.99	C
95875	PKG - Mac 60-70 Head	17.99	B
95878	PKG - Mac 95 Head	23.99	B
95881	PKG - Mac 70-80 Head	23.99	C
95884	PKG - Brush Blade	13.99	C
95886	PKG - 40 Ft. Line	2.49	C
95889	PKG - 30 ft. Line	5.99	C
95892	PKG - 1 lb. of Line	12.99	B
95894	PKG - Spark Arrestor Screen	1.79	B
95896	PKG - Spark Arrestor Screen	2.29	B
95898	PKG - Weed/Grass Blade	8.99	C
95902	PKG - 5 lb. of Line	52.99	A

D. Please add the following part numbers and prices to section 2 (Chains, Bars, Sprocket, and Accessories) in the Master Parts Price list, ADV 140014-R10.

PART NUMBER	DESCRIPTION	MFG. SUGG. LIST PRICE	STOCK CODE
95165	Drum/Sprocket Assembly	$ 7.95	A
95166	Drum/Sprocket Assembly	7.95	A
95197*	Drum/Sprocket/Bearing Assembly	7.49	B
95384**	Drum/Sprocket/Bearing Assembly	7.49	C

*Regular service packaged cloverleaf for consumer saws.
**Display packaged spur for consumer saws.

2. Pro Mac 600 series Bar Adjustment Screw, P/N 94362, was incorrectly printed in the 610/650 I.P.L., P/N 93716-R7, as P/N 94632. When ordering the Bar Adjustment Screw, Figure 4, Item 26, please reference the correct part number, 94362.

3. The following cylinder crankcase/piston assemblies are currently available for service replacement on Super Pro 80, 81, 81E, Pro Mac 850, and Pro Mac 800 series chain saws.

CYLINDER/C'CASE PART NUMBER	USED ON	SPECIAL NOTES
214716 (Formerly 92450D)	Super Pro 80, 81, 81E Series	Contains direct-type manual oiler for backfitting.
95167	Pro Mac 850 Series	Service replacement for all Pro Mac 850 units.
214740	Pro Mac 800 Series	The only replacement cylinder/ crankcase available for Pro Mac 800 series.

McCULLOCH CORPORATION

Product Service Department