McCULLOCH SERVICE BULLETIN

NO. 1715

MODEL: AUTO SHARP EQUIPPED UNITS DATE: December 15, 1981

SUBJECT: AUTO SHARP ASSEMBLY STATUS UPDATE

The AUTO SHARP Assembly used on McCulloch gasoline chain saws has been redesigned for improved retention alignment.

The new AUTO SHARP, P/N 215664, is now being used on all MAC 140 and PM 320/340 saws currently being manufactured. In addition, this assembly can be used as service replacement on Mini Mac 35AS units. It offers several improvements over the previous design.

The body is positively secured onto the new bracket by two captive screws. The knob does not have to be removed to gain access to these screws. This makes it easier to install. There is much less room for consumer error in installation so grinding stone alignment is greatly improved.

NOTE: No attempt should be made to remove the captive screws from the AUTO SHARP body. They are not replaceable service components.

The P/N 215664 assembly, includes the AUTO SHARP assembly and two brackets. One is for MAC 140 and MM35AS series units and the other, stamped with the letter "M", is for PM 300 series units.

NOTE: Enclosed in this kit is Instruction Sheet P/N 96489, which gives complete installation procedures for the new assembly, and, in addition, details the bracket identification procedure.

The new AUTO SHARP kit is now being sold both in regular service packaging (Kit P/N 215664) and in display packaging (Kit P/N 215662).

Electramac saws will continue to use the older design AUTO SHARP. However, these assemblies have been given new part numbers. The ELECTRAMAC AUTO SHARP service package has been identified as P/N 215665, and the display package as P/N 215663. The previously used part number, 94951, has been made "no longer available" (NLA), and may not be ordered under that number.

AUTO SHARP ASSEMBLY	P/N	MFG. SUGGESTED LIST PRICE
MM35AS, MAC 140, PM 310/340, (Service Pkg.)	215664	$7.99
MAC 140, PM 320, (Display Pkg.)	215662	$7.99
ELECTRAMAC (Service Pkg.)	215665	$7.99
ELECTRAMAC (Display Pkg.)	215663	$7.99

AUTO SHARP Assembly, P/N 94951, is "no longer available". However, all previous components for this assembly will remain active under the same part numbers.

McCULLOCH CORPORATION

Product Service Department