McCULLOCH

SERVICE BULLETIN # 1112

SUBJECT NEW STEEL BREAKER BOX COVER

MODEL 1-71, 1-81, 1-81 HD DATE 11/1/60




FIGURE 1




FIGURE 2

A new moisture - and dirt-proof Breaker Box Cover, P/N 55766A (shown in Figure 1 above), is available for service replacement on Model 1-71, 1-81, and 1-81 HD engines. The new steel cover replaces the earlier plastic cover, P/N 55766.

To install the new Breaker Box Cover, follow these instructions:

1. Remove the six retaining screws, four lockplates, two clamps, and the old breaker box cover from the crankcase cover assembly.

2. Put the new Breaker Box Cover over the breaker points and secure with two new Breaker Box Cover Clips, P/N 55977, and four of the original retaining screws just removed (see Figure 1).

3. Reinstall the two clamps with the two remaining screws.

COPYRIGHT 1960 McCULLOCH CORPORATION

LITHO IN U.S.A.